

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Lincoln Agency: REGION 2</th></have<>	County: Lincoln Agency: REGION 2	
1	7.7				Y	minimums	ENTRY POINT	
2	7.7				4	been met for		
3						this day?	EP-B	
4			11			(1	PWS ID 4100925	
5	7.7	P			Y	S	W LINCOLN CO WATER DIST	
6								
7						Sample	period: February 2021	
8	7.7		-		7	Dample	Month/Year	
9		-					14. 1 21.	
10	7.7	-		-	7	Number of	excursions during this month:	
11	7.)	* A - UC)			Y	(Over 9 exc	ursions in 6 months is a violation.	
12						Entry Point	and Distribution excursions are	
13						cumulative).	An 'excursion' is any day in which the	
14							y parameter(s) fall below the minimum	
15						set by the S	MAR 0 5 2021	
16	77						Data Mgmt & Complianc	
17	1, [-7-			7	Refe	rence Drinking Water-Program	
18								
19 20				-		7 4	Minimum Water Quality	
21	-				_		Parameter(s) as set by State:	
22	7				A		pH 7.1	
23	1, 1				-/-			
24	7.6			-	J	on more described to the described of the second	And the second s	
25	/ /					-		
26								
27					\neg		DAROY ADALOS	
28						Print Name: <u>PARRY ARNOLD</u> Signature: <u>Bany Lmold</u>		
29								
30							Phone#: 3-3-21 541-547-4951	
31							DWP within 10 days after end of	
) = N	= Excu	rsion)	Total	N's l	2	samplir	ng period	

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml